



Trade Name: Fiberglass Cloth

Part Number: 2000TP-38

Chemical N/A

Family:

Formula: N/A

Mailing Address:

PO BOX 44226
ATLANTA, GA 30336

Business Phone:

404-699-9900

Business Fax:

404-699-7800

E-mail Address:

info@TECHNIWELDUSA.COM

Web Address:

TECHNIWELDUSA.COM

Emergency Phone:

CHEMTREC (24-Hour) 1-800-424-9300
OUTSIDE OF THE USA OR CANADA 1-703-527-3887

HAZARDOUS INGREDIENTS:

FIBROUS GLASS: CAS # 65997-17-3 99.94%

FIBROUS GLASS DUST: % not known *

* Amount will be dependent upon method of handling.

Exposure Limits: ACGH TLV (Source): 5mg/m³, OSHA PEL (Source): 5mg/m³

PHYSICAL DATA:

Appearance & Odour: Solid, Salmon no odor

Vapour Pressure: 2.00 hPa

Vapour Density: N/A

Solubility in Water: Negligible

Specific Gravity: Approximately 2.5

Evaporation Rate: N/A

Softening Point: Approximately 835°C

Density: 2.560 g/cm³ @ 77°F / 25°C

pH: N/A

FIRE & EXPLOSION DATA:

Flashpoint & Method: N/A

Flammable Limits: N/A

Extinguishing Methods: Water, foam, carbon dioxide, dry chemical

Special Equipment & Procedures: Self contained breathing apparatus and complete protective clothing.

REACTIVITY DATA:

Conditions Contributing to Instability: Stable

Incompatible Substances: None

Hazardous Decomposition Products: Carbon dioxide, carbon monoxide, hydrocarbons, water.

Hazardous Polymerization: Will not occur.

HEALTH HAZARDS DATA:

NOTE: Health studies have shown that exposure to chemicals pose potential risks which may vary from person to person. Exposure to liquids, vapours, mists or fumes should be minimized.

PRINCIPAL HEALTH HAZARDS:

Skin Contact: Minor irritation

Eye Contact: Minor irritation

Ingestion: Minor irritation

Inhalation: Minor irritation

FIRST AID PROCEDURES:

Skin: Wash with soap & water. If irritation persists see physician

Eyes: Flush with water for 15 minutes. If irritation persists see physician.

Ingestion: Give 2 glasses of water. If irritation persists see physician.

Inhalation: Remove to fresh air.

PREVENTIVE MEASURES:

Skin: Always apply appropriate barrier cream to exposed skin. Wear impervious Gloves (butyl rubber), coveralls and safety footwear.

Eyes: Chemical proof goggles or full face respirator if vapours cause eye irritation.

Ingestion: Wash thoroughly before consuming food stuffs.

Inhalation: Use only in well ventilated areas or use NIOSH approved respiratory protection with organic vapour cartridges.

CONTROL MEASURES & PRECAUTIONS

Keep container tightly closed. Do not consume food, drink or tobacco in work area or material storage areas. Use caution and personal cleanliness to avoid skin and eye contact. Avoid breathing vapours of heated materials. Use paper covering absorbent wipes and suitable disposable containers in work area.

SPILL, LEAK & DISPOSAL METHODS

Review fire and explosion hazards and safety precautions before proceeding with clean up. Restrict access to area. Contain spill to prevent dust from entering sewers or waterways. Place in suitable container for disposal.

DISPOSAL METHOD

Dispose only in a facility permitted to dispose of hazardous waste by Federal, Provincial and Municipal regulations.

SHIPPING INFORMATION

Shipping Name:

Hazard Class: Non Regulated

UN/PIN #:

Flashpoint:

WHMIS: D2B

The information contained herein is based on data that we believe to be accurate. No warranty either expressed or implied is made. This information is offered solely for your consideration interpretation and information.

Preparation Date: September 1, 2014

Prepared by: Eddie Johnson , 6205 Boat Rock Blvd, Atlanta GA 30336

Telephone #: (404) 699-9900

Revised Date: December 5, 2014

N/A = Not Available